

HARVEST - 10 FIELD PROCESSING -12 F16. 1 14 - STORAGE 16 SPIRAL CUT PLIGHT CONVEYOR HAMMER MILL - 18 LINT BEATER -20 M!X-40 HOPPER/MIXER ADD SURFACT 142 ACTIVE ACCOUNT 24 - DRKR SZ 26 - LINT BUATER 46 - HEAT 28 - GRINDER (5) ·[REDUCE PRESSURE] 48 - COOL 30 - LINT BEATER (5) 32 - BOWER SHAKER(S) F16.Z SCREEN FOR SIZE - 34 HOLDINGBINS)





## F165

